
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 7/15/2009
Test to be performed: Smoke Dyed Water X Dry ✓ Damp □ Wet □		Supervisor: JAW
Manhole_ID: S091015MH	Test ID: <u>D1032-008018</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S09I025MH
0			Water Level	
88.5	10		Tap Factory Active	From 3311 Elber
88.59999847			Dye Test Visible	@ TFA - toilet
103.3000031			Dye Test Not Visible	@ TFA - downspout
103.3000031			Manhole	S091015MH
103.3000031			End of Survey	DYE TEST COMPLETED